



Note: If Plasterboard cantilevered 75mm or more past the top screw then wall lining must be double layer